


Appendix K:
Utica Harbor Point Redevelopment CM#2
Project, Existing Bulkhead Remedial Concepts,
CME, February 2015



CME
Associates, Inc.

P.O. Box 5490
Syracuse, New York 13220
(315) 668-0242
(315) 668-0256 (Fax)
www.cmeassociates.com

February 11, 2015

Via E-Mail Only

Elan Planning, Design & Landscape Architecture, PLLC
c/o O'Brien & Gere
101 First Street, 4th Floor
Utica, New York 13501

Attn: Mr. Paul D. Romano, P.E. Paul.Romano@obg.com

Re: Utica - Harbor Point Redevelopment CM#2 Project
Existing Bulkhead Remedial Concepts
CME Report No. 26959E-02-0215
Page 1 of 2

Dear Mr. Romano:

Pursuant to our discussion on January 13, 2015, the undersigned engineer has developed a concept for remediation of the Existing Bulkhead, which we feel will be considerable less costly than complete demolition and reconstruction, while maintaining a watermark within about one foot of existing.

1.0 INTRODUCTION

I reviewed the June 12, 2014 Canal Corp Terminal Wall Replacement Estimate of \$13M and the "replacement concept" represented therein, which was taken from a recent Canal Project for Lock E-9, Upper Approach Wall. As we discussed, this solution is way outside of the \$2.5M to \$4M range of possible grant and funding money that may be available for the current Harbor Point Redevelopment CM#2 project.

It is important to point out that the existing distressed concrete and wooden structure is 100 years old and any dependence on any elements of the existing structure for the remediation/redevelopment will involve recognition and acceptance of some risks and uncertainties. These risks and uncertainties include but are not limited to, sudden catastrophic collapse, local or general settlements, and/or sudden sinkhole development. These risks are inherent in the existing structure and current condition. The existing Bulkhead Wall is an 8 foot tall wall of deteriorated concrete, built on a submerged horizontal wooden platform supported by timber piles about 10 feet above the bottom of the harbor. The wall varies in width from about 2.5 feet at top to 6 feet at base and has 3 rows of piles spaced at 4.25 feet apart along its 1300 feet length. The wooden platform is constructed of 12x12 or 12x8 timber framing and 4 inch thick wood planking. The platform is about 16 feet wide. It is just water and piles under the

A New York State Certified Women Owned Business Enterprise (WBE)



platform structure. Please refer to the attached January 1914, Final Estimate – Dock Alteration No. 1 Drawing for more information on what was planned to be built. It should be noted that the existing Dock and Wall does not conform exactly to this drawing. For example, the existing structure has about 100 piles less than what is shown in the 1914 Drawing.

CME's focus in this effort has been to present a solution that preserves the real estate (i.e. does not give up land to water); reduces the risk of sudden catastrophic collapse; reduces the risk of significant or very costly change orders during the construction by reducing the design concept's dependence on existing load bearing elements; and minimizing Total Project Cost.

2.0 CONCEPTS

CME's first concept studied was to install a temporary sheetpile cofferdam, lower the water, demolish the existing concrete wall, remove the soil above the submerged wooden platform deck, and remove the deck and timber framing. Then inspect the piles and drive intermediate piles, as-needed. Reconstruct the wood deck and a new concrete bulkhead, backfill and pave/surface, and then remove the cofferdam.

CME's second concept studied was to install a permanent light gauge sheetpile cofferdam wall, demolish a portion of existing concrete wall, partially dewater, and use Cellular Controlled Density Fill (CCDF) to fill the entire void space between the light gauge sheetpile wall and land under the deck. Install waler and deadman tiebacks for wall, backfill and pave/surface.

CME's second concept is presented on the attached sketch and is intended for discussion purposes. This concept is about 50% less costly than the first concept and, since the new Bulkhead Wall will be completely backfilled to the mudline, represents a much lower risk alternative by eliminating the sudden collapse and sinkhole risks.

3.0 RECOMMENDATIONS

It is recommended that the Concept Sketch be considered and discussed. If no other significantly different concepts are envisioned that capture the attributes desired, then Design Development of the concept should commence.

Please direct all inquiries and discussion to the undersigned engineer.

Respectfully submitted,

CME Associates, Inc.


A handwritten signature in dark ink, appearing to read "Marcus A. Rotundo", is written over the company name.

Marcus A. Rotundo, P.E.
Sr. Geotechnical Engineer

MAR/jll


Attachment Listing: 1914 Final Estimate Dock Alteration No. 1, Utica Terminal (1 of 1)
Concept Sketch (1 of 1)

MADE IN THE
CHANDLER
DIVISION OF THE U.S. ARMY





TERMINAL CONDUIT NO. 15
LOCALITY: OFFICE, N.Y.
DATE: 10-1-50
BY: [Signature]

FINAL ESTIMATE Cost. Alteration No. 1



SECTION A-A


FOUNDATION PLAN OF PILES




DATE: 10-1-50
BY: [Signature]

CONCEPT SKETCH

CME REPORT NO. 26959E-02-0215





CME
Associates, Inc.

P.O. Box 5490
Syracuse, New York 13220
(315) 668-0242
(315) 668-0256 (Fax)
www.cmeassociates.com

February 11, 2015

Via E-Mail Only

Elan Planning, Design & Landscape Architecture, PLLC
c/o O'Brien & Gere
101 First Street, 4th Floor
Utica, New York 13501

Attn: Mr. Paul D. Romano, P.E. Paul.Romano@obg.com

Re: Utica - Harbor Point Redevelopment CM#2 Project
Canal Corp Inspection of Structure of September 19, 2008
CME Report No. 26959E-01-0215
Page 1 of 2

Dear Mr. Romano:

At your request, the undersigned engineer evaluated the NYSCC Structure Inspection Report STRIN: 400T54A of September 19, 2008 in respect to reliance on and re-use of any of the structure components.

I noted some apparent discrepancies between the January 1914 Final Estimate Dock Alteration No. 1 Documents and the Inspection Report of 2008. They are:

- The wood triple-lap sheeting may not exist or was not installed in 1914.
- The rip-rap may only be a few feet thick and laid on an earth slope.
- The rip-rap slope angle is likely steeper than shown on the 1914 Drawing.
- The piles are 4.25 feet on-center along the lines parallel with the existing concrete wall, not 4 feet on-center as shown on 1914 Drawing.
- One of the two 8x10 timbers to serve as keyways for the concrete wall, may be located at the outside face toe of Wall.

I catalogued the underwater inspection notes for the 4 rows of piles into five categories which are indicators of structural integrity impairment. They are:

L – Cross Section Loss of 10% or more
D – Displaced Horizontally
X – No contact pile to Pile Cap or at least 75% bearing impaired
x – Bearing impaired 50% to 75%
S – Pile Split or Pile Cap Crushed/Split

A New York State Certified Women Owned Business Enterprise (WBE)



The inspection Starts at about station 0+60 and Ends at station 12+96 for 304 Rows of four vertical piles each for 1216 piles total. The Batter Piles are not mentioned in the Inspection Report.

My Findings are presented in Table 1. Row 1 is at the outboard toe of existing Bulkhead Wall.

Table 1: Summary of Five Structural Defects of Piles					
ROW	1	2	3	4	Line Totals
Defect					
L	35	12	9	4	60
D	42	74	59	24	199
X	8	22	29	32	91
x	30	20	19	5	74
S	46	24	20	8	98
TOTALS	161	152	136	73	522
Cum. Total	161	313	449	522	522
Cum. %	31%	60%	96%	100%	100%

We have attached the Annotated Inspection Report showing the location of each Defect, among other notations.

Because Pile Rows 1, 2 and 3 support the existing wall with 912 piles and since 49% (449 piles) exhibited significant defects in 2008, CME has concluded that it is not prudent to proceed with any design which relies on utilizing the existing timber piles for structural support. In our professional opinion, this Bulkhead and submerged wooded platform have reached the end of their useful life.

At this date, one must understand that failure of the wall and/or platform could occur at any time. Failure may be manifested by sudden collapse, sinkhole, slide into Harbor, and progressive settlement of surfaces on, near and/or around the structure.

Please contact the undersigned with any questions that you may have.

Respectfully submitted,



CME Associates, Inc.

A handwritten signature in black ink, appearing to read "Marcus A. Rotundo", is written over a faint, larger version of the same signature.

Marcus A. Rotundo, P.E.
Sr. Geotechnical Engineer


MAR/jll

Attachment Listing: Annotated Structure Inspection Report (34 pages)
 Final Estimate January 1914, p. 19 (1 page)




SECTION A-A

FOUNDATION PLAN OF PILES



BLOCKS NO. 1 & 33



MALIBU BEACH, CALIF. 90263
CHILDREN'S DIVISION
DIVISION CHIEF: E. J. SUTHERLAND



Structure Inspection Report

STRIN: 400T54A

Structure Name: Terminal - Utica

Division: Syracuse

Section: Utica

Inspection Completion Date: 09/19/2008

General Condition Rating: 4

There are no addendums to this report.

Annotations By:
MARCUS ROTUNDO
CME ASSOCIATES INC
2/10/2015

Structure Inspection Report

STRIN: 400T54A

Inspection Completion Date: 09/19/2008

STRIN: 400T54A

Structure Name: Terminal - Utica

Inspection Type: Special, Below Water

Approval Status: Approved

Completed Date: 9/19/2008

General Condition Rating: 4

Work Urgency Index: 6

Inspection Performed By: Collins Engineering, P.C.

Team Leader: Heath Pope, P.E.

PE Number: 085945-1

Assistant Team Leader:

Other/Speciality: Frank Lasch, Jaime Stewart

Sub Consultant:

Summary Remarks:

The wall is in fair condition. The eastern concrete wall face has moderate scaling over 100% of the face, many large spalls, and a number of cracks in the face. The southern wall face has light scaling over 50% of the face with minor spalls and is in better shape overall. The timber piles, decking, and cap beams have moderate rot and deterioration. Many piles have 10% section loss on the upper 2 - 4'. The timber fender system is missing over 80% of the structure. Notes for the piles are located at the end of the drawings sheets.

Notes For Next Inspector:

None

Activity Log

Date	Arrival Time	Depart Time	Low Temp (F°)	High Temp (F°)	Weather	Access	Remarks
9/17/2008	8:00 AM	4:00 PM	62	65	Cloudy	Diving;	Swim-by Inspection
9/18/2008	9:00 AM	5:00 PM	70	72	Fair	Diving;	Swim-by Inspection
9/19/2009	9:00 AM	5:00 PM	75	80	Clear	Diving;	Swim-by Inspection

Inspection Approvals

Approver	PE Number	Approval Type	Approval Date
mackp	47963	Consultant Quality Control	6/26/2009
frasier		Division Approval	7/7/2009
schollen		Headquarters Approval	7/7/2009

Necessary Repairs

Rating	Category	Code	Quan- tity	WUI	Remarks
.101 Exposed Face (1)	Structural Materials	concrete, formed (CY)	41	6	Repair wall face.
.102 Top Face (1)	Structural Materials	concrete, formed (CY)	15	6	Repair/Recap the top of wall.

Inspection Ratings Section

Structure Inspection Report


STRIN: 400T54A

Inspection Completion Date: 09/19/2008


	Inspection Item	Rating	Notes
.100	Walls (1)	4	(none)
.101	Exposed Face (1)	4	(none)
.102	Top Face (1)	4	(none)
.103	Footing (1)	4	(none)
.104	Horizontal Alignment (1)	3	(none)
.105	Vertical Alignment (1)	5	(none)
.106	Fendering System (1)	1	(none)
.200	Bollards (1)	0	(none)
.300	Ladders (1)	0	(none)
.400	Adjacent Earth (1)	0	(none)
.500	Pile Clusters (1)	0	(none)
.600	Lighting or Reflectors (1)	0	(none)
.700	Guide Piers (1)	0	(none)
.701	Concrete (1)	0	(none)
.702	Timber (1)	0	(none)
.703	Steel Sheet Pile (1)	0	(none)
.800	Pavement (1)	0	(none)
.900	Grounds (1)	0	(none)

Inspection Images Section


*Sketches, drawings, and photographs relevant to
the structure in general.*



LOCATION




PLAN VIEW



- L- Cross Section Loss 10% or More
- D- Displaced Horizontally
- ⊗- No Contact with Pile Cap or ≥ 75% Barring Impaired
- X- Barring Impaired 50% or more
- S- Pile Cap - crushed/split or split Pile


ELEVATION VIEW



ELEVATION VIEW

General Notes:

See page 8 for Notes.



ELEVATION VIEW


General Notes:
See page 8 for Notes.

Rows

④
⑧
②
①

5+00

6+00



92 94 96 98 100 102 104 106 108 110 112 114 116 118 120 122 124 126 128 130 132 134


0'	12.2	12.0	11.6	10.8	10.7	10.7	11.2	11.1	10.7	12.0	12.2	13.0	12.6	12.1	10.6	10.0	10.0	9.5
6"	-	12.9	-	12.8	-	13.0	-	12.7	-	13.2	-	14.9	-	13.2	-	12.0	-	10.3
10"	-	13.2	-	13.0	-	13.5	-	13.0	-	13.8	-	14.8	-	13.0	-	12.2	-	10.6

n=59

ELEVATION VIEW
(N.T.S.)

ELEVATION VIEW

General Notes:
See page 8 for Notes.



139 ① Crushed

140 ① Crushed

148-156 All Rows - Not Inspected


157 - Drain Pipe

161-162 - CS poor condition

ELEVATION VIEW

174 - Sheet Pile?

General Notes:
See page 8 for Notes.



181-182 CJ - spalled

181-182 - Beam between pile caps 50% loss-x

179-180 - do


201-202 CJ - spalled

216-217 Beam broken

ELEVATION VIEW

221 - End Cap Split

General Notes:
See page 8 for Notes.



233 - ② Rip-Rap to Row 2 on angle

234-235 - CT - 50% Section Loss, spalling to bottom

237 - same as old report

240 ③ Rip-Rap

241 - ?

ELEVATION VIEW

242 ④ Rip Rap

244-245 Penetrating hole goes up @ 45° angle

246 ③ Rip Rap

249 ④ Rip Rap @ 393±

255 ⑤ Rip-Rap


260 ③ Rip-Rap

General Notes:

See page 8 for Notes.

ROWS

④
⑤
②
①



270	272	274	276	278	280	282	284	286	288	290	292	294	296	298	300	302	304
0'	11.0	11.7	11.8	11.8	11.0	10.4	9.5	8.8	7.2	2.5	0.0	+1	+2				
6'	-	12.4	-	12.4	-	10.7	-	8.8	-	2.6	-	0.0	-				
10'	-	12.5	-	12.8	-	11.5	-	9.1	-	2.3	-	0.0	-				

$n=126$

ELEVATION VIEW

(N.T.S.)

294-③ kip-Rap

301-③ kip-Rap

303-① kip-Rap

ELEVATION VIEW

PILE NOTES:

Pile 4 / Row 1: Top 3' missing 10% of cross section

Pile 8 / Row 1: About 10% left but pushed out from pier

Pile 10 / Row 1: Top 4' missing 10% of cross section

Pile 11 & 12 / Row 1: Construction Joint, 2' to top of wall
Heavy Scaling, extends 1' to either side of joint
Maximum Penetration

Pile 12 / Row 1: Spalling 2-4" Deep, 1' Wide
Extends to surface to timber
1/2" wide crack

Pile 13 / Row 1: Pile split into 2, approx. 2' in length
25% section loss in pile

Pile 14 / Row 1: 10% section loss
6" penetration / 2" wide

Pile 15 / Row 1: Pile cap split

Pile 16 / Row 1: Offset 6"
Split in half with 50% section loss
Impact damage
Approx. 50% is bearing weight

Pile 17 / Row 1: 30% section loss

Pile 18 / Row 1: Split pile going all the way through
Approx. 50% is bearing weight

Pile 20: 20% of pile underneath pile cap
Pile has shifted but no horizontal bearing

Pile 21: Spalling at joint
Heavy Scaling

Pile 21 / Row 3: Approx. 50% is bearing weight

Pile 22 / Row 2: Approx. 50% is bearing weight

Pile 24 / Row 1: 20% section loss

Pile 26 / Row 1: 20% section loss

Pile 26 / Row 2: Split 1" wide, down 2' from wall, 3-4" penetration

Pile 26 / Row 3: Approx. 75% is bearing weight

Pile 27 / Row 1: 10% section loss

Pile 28 / Row 1: 20% section loss

Pile 38 / Row 3: 75% of pile under cap

Pile 39 / Row 1: Multiple splits down 2'
Approx. 75% is bearing weight

Pile 39 / Row 3: Pile does not touch pile cap, 2" gap

Pile 40 / Row 2: Approx. 75% is bearing weight

Pile 43 / Row 1: Top 1' missing 10% of material

Pile 44 / Row 1: Top 3' missing 10% of material
20% section loss in pile

Pile 45 / Row 1: 10% section loss

Pile 46 / Row 1: Split through pile
20% section loss

Pile 52 / Row 3: 2 splits, 1" wide, 2' long, 3-4" penetration
Heavy scaling @ concrete joint
Extend 1' below water to top of wall
Extends horizontal 1-2', 6" Max. Pen., 2" Typical

Pile 53 / Row 3: Pile does not touch pile cap, 1" gap

Pile 54 / Row 3: 50% of pile underneath pile cap

Pile 56 / Row 3: Approx. 75% is bearing weight

Pile 58 & 59: Piles are closer than typical spacing

Pile 61 / Row 2: Pile does not touch pile cap, 1" gap

Pile 62: ??????

Pile 64 / Row 2: Split from top of pile, down 3'

Pile 63 & 64: ???????

Pile 72 / Row 2: Pile does not touch pile cap, 1" gap
2 1/2" split from top of pile, down 1'
Heavy scaling ?????

Pile 73 / Row 1 & 2: Offset 4" to left

Pile 73 / Row 4: Riprap around pile at channel bottom

Pile 75 / Row 1: 5% section loss

Pile 76 / Row 1 & 2: Offset 3"

Pile 76 / Row 4: Pile does not touch pile cap, 1/2" gap

Pile 77 / Row 1: Offset 3"

Pile 77 / Row 2: Split through pile, 1/2" wide x 1' long

Pile 77 / Row 3: 50% of pile touches pile cap, 1/2" gap

Pile 77 / Row 4: 10% section loss

Pile 78 / Row 1 & 2: Offset 3"

Pile 78 / Row 3 & 4: Piles do not touch pile cap, 1/2" gap

Pile 79 / Row 4: Pile does not touch pile cap, 1/2" gap
Offset 4"

Pile 80 / Row 1: 2" split, down 3'
50% section loss

Pile 80 / Row 4: Offset 2"
Pile does not touch pile cap, 1/2" gap

Pile 81 / Row 1: 1" wide split through pile, down 2'
25% section loss

Pile 81 / Row 3: Offset 4"

Pile 81 / Row 4: 1" wide split through pile, down 2' into rip rap

Pile 82 / Row 4: 2" wide split through pile, down 3'

Pile 83 / Row 2: Offset 2"

Pile 83 / Row 3: 3" wide split through pile, down 3'
25% section loss

Pile 84 / Row 3: Pile does not touch pile cap, 1/2" gap
1" wide split, 3' long, 3" penetration

Pile 84 / Row 4: Offset 6"
4" wide split, from top to 6" above rip rap, 4" penetration
50% section loss

Pile 85 / Row 1: Pile cap severed, 1 1/2' hanging off, 6" of pile cap

Pile 85 / Row 2: Offset 4"

Pile 85 / Row 3: 1/2" split, down 4', 1" penetration

Pile 86 / Row 1 & 2: Offset 4"

Pile 86 / Row 4: Pile does not touch pile cap, 1/2" gap

Pile 88 / Row 1: 1" split through pile, down 2'
20% section loss

Pile Q's
73-

PILE NOTES

PILE NOTES:

Pile 89 / Row 3: Offset 4" 2" Split through pile, down 4' 25% section loss	Pile 100 / Row 1: Offset 3"	Pile 118 / Row 4: 75% of pile does not touch pile cap, 1/2" gap
Pile 89 / Row 4: Offset 6"	Pile 100 / Row 2: Offset 12" Pile does not touch pile cap	Pile 119 / Row 2: Offset 4" 50% of pile does not touch pile cap, 1/2" gap
Pile 90 / Row 1: 1" wide split through pile, down 3' 50% section loss	Pile 101 / Row 1: 25% section loss	Pile 120 / Row 2 & 4: Offset 4"
Pile 90 / Row 2 & 3: Offset 3"	Pile 101 / Row 3: Offset 3"	Pile 120 / Row 3: Offset 6" Pile does not touch pile cap, 1/2" gap
Pile 90 / Row 4: 1" split, down 2"	Pile 101 / Row 4: Pile does not touch pile cap, 1/2" gap	Pile 121 / Row 2 & 3: Offset 4"
Pile 91 / Row 2: 1" wide split through pile, down 3' 50% section loss	Pile 102 / Row 1: Offset 2"	Pile 122 / Row 2: 5% section loss
????? Look at notes ?????	Pile 102 / Row 4: Pile does not touch pile cap, 1" gap	Pile 122 / Row 3: 10% section loss 1/2" wide split, 1" long, 1" penetration
Pile 92 / Row 3: 1/2" wide split, down 2' 25% section loss	Pile 103 / Row 2: Offset 2"	Pile 123 / Row 1 & 3: Offset 4"
Pile 92 / Row 4: Pile does not touch pile cap, 1" gap	Pile 104 / Row 1 & 3: Offset 3"	Pile 123 / Row 2: 50% section loss 2 splits 2" wide, down 2'
Pile 93 / Row 2 & 3: Offset 6"	Pile 105 / Row 3: Offset 3"	Pile 124 / Row 1: 1/2" split, 1' long
Pile 94 / Row 3 & 4: Offset 4"	Pile 106 / Row 1: 10% section loss	Pile 124 / Row 2: 10% section loss
Pile 95 / Row 1: Pile cap end, 3" wide crack from top to bottom, 6" penetration, extends 1' past pile	Pile 106 / Row 3 & 4: Pile does not touch the pile cap, 1" gap	Pile 124 / Row 3: 25% section loss
Pile 95 / Row 2: Offset 4"	Pile 107 / Row 2: Offset 4" Pile does not touch pile cap, 1/2" gap	Pile 124 / Row 4: Pile does not touch pile cap, 2" gap
Pile 95 / Row 4: Pile does not touch pile cap, 2" gap	Pile 107 / Row 4: Offset 12" Pile is not under the pile cap	Pile 125 / Row 2: 1/2" split through pile, down 1'
Pile 96 / Row 1: 10% section loss	Pile 108 / Row 3: Offset 6"	Pile 125 / Row 3: Offset 3"
Pile 96 / Row 3: Offset 6" 10% section loss	Pile 110 / Row 3: 5% section loss	Pile 126 / Row 1: Split through pile, down 1'
Pile 96 / Row 4: Pile does not touch pile cap, 1/2" gap	Pile 112 / Row 2: 50% of pile does not touch pile cap, 1/2" gap	Pile 126 / Row 3: Offset 3" 1/2" split, 2" penetration, down 1'
Pile 97 / Row 1: 15% section loss	Pile 112 / Row 3: Offset 3"	Pile 126 / Row 4: Offset 3"
Pile 98 / Row 1 & 3: Offset 4"	Pile 112 / Row 4: Pile does not touch pile, 1/2" gap	Pile 127 / Row 2: Pile does not touch pile cap, 1/2" gap
Pile 99 / Row 1: Offset 2"	Pile 113 / Row 2 & 4: Offset 5"	Pile 128 / Row 1: 10% section loss
Pile 99 / Row 2: Pile does not touch pile cap, 1" gap Offset 4"	Pile 114 / Row 1: Offset 4"	Pile 128 / Row 2: 1/2" split, 1" penetration
Pile 99 / Row 3: Offset 3"	Pile 114 / Row 2: 1/2" split, down 1'	Pile 128 / Row 3: Offset 4" 90% of pile does not touch pile cap
	Pile 114 / Row 4: 10% section loss	Pile 128 / Row 4: Offset 3"
	Pile 117 / Row 1: 10% section loss	
	Pile 117 / Row 4: Pile does not touch pile cap, 1" gap	

PILE NOTES

PILE NOTES:

Pile 129: End of pile cap: 3" wide split, 6" penetration	Pile 139 / Row 3: 1/2" GAP, 50% Touching	Pile 160 / Row 4: 1/2" gap, not engaged
Pile 130 / Row 1: Offset 3"	Pile 140 / Row 1: 15% section loss Split on end of cap all the way through 4" penetration, 2" wide	Pile 161 / Row 1: Offset 3" to left
Pile 130 / Row 2: Offset 8" 90% of pile does not touch pile cap	Pile 141 / Row 2: Offset 2" to left	Pile 161 / Row 3: 1/2" gap, no engagement
Pile 130 / Row 3: Offset 6" Split down middle, 2' long 50% section loss	Pile 141 / Row 3: Full depth split, 1" wide, 3' down 25% section loss	Pile 161 / Row 4: Offset 2" to right
Pile 130 / Row 4: Offset 5"	Pile 142 / Row 3: Full depth split, 2' long 25% section loss	Piles 161-162: Construction Joint 6'-1' penetration, top to 6" below WL 2' horizontally Similar to previous notes
Pile 131 / Row 1: 2" wide split, 4' long 50% section loss	Pile 143 / Row 1: 5% section loss	Pile 162 / Row 2: Offset 4" to right
Pile 131 / Row 2: 75% of pile does not touch pile cap, 1" gap	Pile 143 / Row 4: Offset 2" to left	Pile 162 / Row 3: Offset 4" to left
Pile 132 / Row 2: 2" wide split through pile, 1' long 25% section loss	Pile 144 / Row 1: Offset 3" to left	Pile 162 / Row 4: Offset 4" to right
Pile 132 / Row 3: 75% section loss 4" wide split down center, 5' long	Pile 145 / Row 1: 5% section loss	Pile 163 / Row 2: Offset 6" to left
Pile 133 / Row 1: 10% section loss	Pile 145 / Row 2: Offset 4" to left 5% section loss	Pile 163 / Row 3: 1/2" gap, 50% engaged
Pile 133 / Row 2: Offset 6" 15% section loss	Pile 145 / Row 3: Offset 6" to right	Pile 163 / Row 4: 1/2" gap, 50% engaged
Pile 133 / Row 4: 4" split down center 100% section loss	Pile 145 / Row 4: Offset 4" to left	Pile 164 / Row 4: Offset 3" to left
Pile 134 / Row 3: 75% of pile does not touch pile cap, 1" gap	Pile 146 / Row 1: 5% section loss	Pile 165 / Row 1: 10% section loss
Pile 134 / Row 4: Offset 4" End of pile cap: 3" wide split, 4" penetration	Pile 146 / Row 2: Split, 2" wide, 4' down	Pile 165 / Row 2: 3" wide split goes down 3' 50% section loss
Pile 135 / Row 1: 5% section loss	Pile 147 / Row 2: Offset 3" to left Pile cap from end to Pile 2 15% section loss	Pile 165 / Row 3: Offset 4" to right 60% of pile engaged
Pile 136 / Row 2: 5% section loss	Piles 148-156 NEEDED	Pile 165 / Row 4: 1" gap, split down middle 1' long 100% NOT engaged
Pile 136 / Row 4: Pile does not touch pile cap, 1" gap	Pile 157 / Row 1: 6" gap from bottom to concrete	Pile 166 / Row 1: Offset 5" to right 50% engaged
Pile 137 / Row 4: 75% of pile does not touch pile cap, 1/2" gap	Pile 157 / Row 2: 2" horizontal, 4" penetration Spalling at drain pipe	Pile 166 / Row 2: Offset 4" to left, 1/2" gap 100" of pile not engaged
Pile 138 / Row 4: Pile does not touch pile cap, 1" gap	Pile 158 / Row 3: 10-12" shift right of pile cap, no contact	Pile 167: 4" of end of pile cap deteriorated Drift pin exposed 5% section loss
Pile 139 / Row 1: Pile cap: 2-3" wide split, top to bottom 2" cap crushed down	Pile 158 / Row 4: Offset 3" to left	Pile 167 / Row 2: 10% section loss
Pile 139 / Row 2: Offset 4"	Pile 160 / Row 1: 10% section loss	Pile 167 / Row 3: Split from top 3' down, 1" wide
	Pile 160 / Row 3: 6" offset to right	

Piles 148-156 NEEDED?

PILE NOTES

PILE NOTES:

Pile 168 / Row 4: ½" gap, 50% engaged	Pile 177 / Row 3: Rip rap 1" gap between pile and cap	Pile 183 / Row 4: Offset 1" to left
Pile 169 / Row 1: Split on front face, 2' long, 2" wide	Pile 178 / Row 1: Offset 3" to left General not on end of pile cap	Pile 184 / Notes: Second pile! Double piles – extra pile not engaged
Pile 169 / Row 2: Offset 4" to left	Pile 178 / Row 2: Section loss of 6" length, 6-8" height, 4" deep 80% deteriorating (above Pile 2)	Pile 184 / Row 1: 5% section loss
Pile 169 / Row 4: Offset 4" to right	Pile 178 / Row 3: 4" split on backside, goes all the way through 1" gap	Pile 185 / Notes: General note for pile cap
Pile 170 / Row 4: 1" gap, 50% engaged	Pile 179 / Notes: General split at end cap	Pile 185 / Row 1: Offset 3" to right
Pile 171 / Row 1: 5% section loss	Pile 179 / Row 1: Offset 3" to right	Pile 185 / Row 2: Offset 4" to left
Pile 171 / Row 2: ½" gap, 50% engaged	Pile 179 / Row 2: Offset 7-8" 3" touching	Pile 185 / Row 3: 20% section loss to whole pile
Pile 171 / Row 3: 1" gap, 100% pile not attached	Pile 179 / Row 3: Offset 3" to left	Pile 186 / Row 1: Offset 3" to right and 3" out
Pile 171 / Row 4: Offset 1' to left, 100% not engaged	Pile 179 / Row 4: Not touching by ½-1"	Pile 186 / Row 2: Offset 2" to right
Pile 172 / Row 3: 1½" gap, 50% pile engaged	Spall at Construction Joint at Piles 181 and 182, 1' x 3" x 3"	Pile 186 / Row 3: Offset 3" to right
Pile 172 / Row 4: 2-3" split from top down 3' 50% pile engaged	Pile 180 / Notes: Horizontal beam from pile cap to pile cap 50% section loss from 179-180	Pile 187 / Row 2: Offset 3" to left 15% section loss
Pile 173 / Row 2: Offset 4" to right	Pile 180 / Row 3: Offset 4" to left	Pile 187 / Row 3: Offset 2" to left
Pile 173 / Row 4: Offset 4" to right ½" gap to top Rip rap	Pile 180 / Row 4: Offset 3" to right	Pile 188 / Row 1: End of pile cap – general note
Pile 174 / Notes: sheet pile	Pile 181 / Row 1: Offset 3" to left	Pile 188 / Row 2: Offset 2" to left
Pile 174 / Row 1: Offset 2" to right	Pile 181 / Row 2: Offset 4" to left	Pile 188 / Row 3: Offset 2" to right
Pile 174 / Row 2: Offset 4" to left	Pile 181 / Row 3: Offset 4" to right	Pile 189 / Row 1: End of pile cap – general note
Pile 174 / Row 3: Offset 2" to right	Pile 181 / Row 4: Not engaged, 1" gap at top	Pile 189 / Row 2: Offset 3" to left
Pile 175 / Notes: 8" length, 4" down split	Pile 182 / Row 1: 20% section loss from top down 6"	Pile 189 / Row 3: Riprap
Pile 175 / Row 3: Offset 4" to right	Pile 182 / Row 3: Offset 3" to left	Piles 189-190 / Notes: End of pile cap – general note
Pile 176 / Row 1: 12" from top of pile going down 30% section loss	Pile 182 / Row 4: Riprap starts, waist high and goes inward to concrete wall in the back Distance from row to wall is approx. 4 feet	Pile 190 / Row 2: Offset 5" to right
Pile 176 / Row 2: Offset 2"	Pile 183 / Row 2: Offset 3" to left	Pile 190 / Row 3: Offset 5" to left
Pile 176 / Row 3: Offset 3" to left	Pile 183 / Row 3: Not engaged, 1" gap to top	Pile 190 / Row 4: Pile not touching cap, 1" gap
Pile 177 / Row 1: Offset 3" to left		Pile 191 / Notes: Crack at end of pile cap. 3" deep, 1" wide
Pile 177 / Row 2: 15% section loss		Pile 191 / Row 3: Offset 4" to left
		Pile 191 / Row 4: Offset 5" to left

182 - Rip-rap
185 - pile cap General Note
183-⑤ R-R

PILE NOTES

PILE NOTES:

Pile 192 / Row 2: Offset 4" to left Not touching with 4" gap	Pile 198 / Row 2: Offset 6" to right	Pile 208 / Row 3: Offset 3" to left
Pile 192 / Row 3: Offset 4" to right 20% section loss 1" down section loss = 50%	Pile 199 / Row 1: Offset 4" to right General note on splitting	Pile 209 / Row 1: Offset 3" to left
Pile 193 / Row 1: Offset 5" to right 5% section loss	Pile 199 / Row 2: Offset 6" to left	Pile 209 / Row 2: Offset 1" to right
Pile 193 / Row 2: 1" touching pile cap Some missing plank horizontally	Pile 199 / Row 3: Offset 5" to right	Pile 209 / Row 3: General splitting note Rip rap
Pile 193 / Row 3: Touching 1" from pile to cap	Pile 200 / Row 1: 5% section loss Offset 4"	Pile 210 / Row 3: 50% is touching pile cap
Pile 193 / Row 4: Splits 1'-2" in length, 2" wide, 4" penetration Offset 4" to right	Pile 200 / Row 2: Offset 3" to right	Pile 211 / Row 1: Offset 2" to right
Pile 194 / Row 1: Pile split down 2' 3" gap at face 4" gap at back Offset 4" to left End of pile cap has various splits	Pile 201 / Row 3: Rip rap Offset 3" to left	Pile 211 / Row 2: Offset 4" to right
Pile 194 / Row 2: Offset 4" to right	In Joint Between 201-202: Spalling from joint to timber 4" penetration	Pile 211 / Row 3: Offset 5" to right 10% touching pile cap
Pile 194 / Row 3: Not touching, 2" separation	Pile 202 / Row 1: Offset 4" to left	Pile 213 / Row 3: Offset 4" to right
Pile 194 / Row 4: Offset to right	Pile 202 / Row 2: Offset 4" to right	Pile 215 / Pile Cap: Split end cap top to bottom, 3" wide, 8' deep
Pile 195 / Row 1: Offset 3" to front	Pile 202 / Row 3: 5" to right of cap	Pile 215 / Row 1: Offset 2" to right
Pile 195 / Row 2: Offset 5" to right Split down middle about 2'; 1" split all the way through	Pile 203 / Row 1: Offset 2" to left	Pile 215 / Row 2: Offset 3" to right
Pile 195 / Row 3: Not touching, 1" separation	Pile 203 / Row 3: 1" gap between pile and pile cap	Pile 215 / Row 3: Offset 3" to right
Pile 196 / Row 1: Offset 2" to right	Pile 204 / Row 1: Offset 2" to right	Pile 216 / Row 1: Offset 2" to left
Pile 196 / Row 2: 1.5" penetration Offset 5" to left No load bearing at all	Pile 204 / Row 3: 2" gap between pile and pile cap	Pile 216 / Row 3: Offset 6" to right
Pile 197 / Row 2: Offset 3" to left	Pile 205 / Row 2: 1" clearance between pile and pile cap	Piles 216-217 / Notes: Horizontal piece broken between 216 and 217
Pile 197 / Row 3: Offset 4" to left Rip rap	Pile 206 / Row 1: Offset 1" to right	Pile 217 / Row 1: Horizontal split Split 2.5" down from top to bottom
Pile 198 / Row 1: Offset 3" to right End cap has vertical split 4" penetration	Pile 206 / Row 2: 1" clearance between pile and pile cap Angled 20° towards Row 1	Pile 218 / Row 1: Offset 3" to left
	Pile 207 / Row 1: Split 1' long 20% section loss	Pile 219 / Row 2: Split in pile, goes down 2' Offset 3" to right 10% section loss
	Pile 207 / Row 2: Offset 3" to right Angled about 25% forward towards Row 1	Pile 219 / Row 3: 10% section loss
	Pile 207 / Row 3: Offset 3" to right	Pile 220 / Row 1: Offset 2" to left
	Pile 208 / Row 1: Split 2' long, all way through 20% section loss	Pile 220 / Row 3: Split from top, 4.5" wide, 2' down Offset 8" to right No contact between cap and pile
	Pile 208 / Row 2: Offset 2" to right	Pile 221 / Notes: End cap split top to bottom, 3" penetration

201 (S) Rip-rap

PILE NOTES

PILE NOTES:

Pile 221 / Row 2: 25% section loss
Split 2" down
Offset 2" to right of pile cap

Pile 221 / Row 3: General note on splitting

Pile 222 / Row 1: Offset 2" to right

Pile 222 / Row 2: Major split, 4" split
25% touching pile cap
40% section loss

Piles 223-224: Horizontal wood is breaking at edge of concrete, dropped down about 5"

Pile 224 / Notes: End cap split

Pile 225 / Row 1: 20% section loss
End of pile cap split from top to bottom, 1" wide, 4" penetration

Pile 225 / Row 2: Offset 3" to left

Pile 225 / Row 3: 50% is touching, 1" gap

Pile 226 / Notes: End of pile cap split from top to bottom, 1" wide, 4" penetration

Pile 227 / Row 3: Offset 3" to right

Pile 227 / Row 4: Large amount of splitting
Pile cap is broken

Pile 228 / Notes: End of pile cap has split, 4" penetration

Pile 228 / Row 1: Split in half, down 5'
50% section loss

Pile 228 / Row 3: 5% section loss

Pile 229 / Row 1: 10% section loss

Pile 229 / Row 3: Offset 3" to right

Pile 229 / Row 4: Offset 3" to left

Pile 230 / Row 1: Offset 5" to right
40% section loss

Pile 230 / Row 2: Offset 2" to left

Pile 231 / Row 1: 50% section loss
Offset 2"

Pile 231 / Row 3: 1" space between pile and cap

Pile 233 / Row 2: Rip rap comes from Row 3 at an angle

Pile 234 / Row 2: Offset 2" to right

Pile 234 / Row 3: Offset 2" to right

Construction Joint: Spalling goes to bottom of concrete
50% section loss

Pile 235 / Row 3: Offset 3" to left

Pile 235 / Row 4: Offset 6" to left
Multiple splits
15% section loss

Pile 236 / Row 2: Offset 3" to left

Pile 237 / Row 1: Same as old report

Pile 237 / Row 2: Offset 4" to right

Pile 237 / Row 3: 1.5" between pile and pile cap

Pile 238 / Row 2: Offset 3" to right

Pile 238 / Row 3: Not touching pile cap by 2"

Pile 239 / Row 1: Offset 1" to right

Pile 239 / Row 2: Offset 4" to left

Pile 240 / Row 1: 5% section loss

Pile 240 / Row 3: Offset 2" to right
Rip rap

Pile 241 / Row 1: Comes up 1.5' out of water, missing the rest

Pile 242 / Row 1: 30-40% section loss from first 2'

Pile 242 / Row 2: Offset 4" to left

Pile 242 / Row 4: Rip rap

Pile 243 / Row 1: Offset 2" left of pile cap
Split, 2" long, 2" wide, 2" penetration

Pile 243 / Row 2: General note for splitting

Pile 244 / Row 1: 15% section loss

Pile 244 / Row 2: Split, 2' x 2'

Pile 244 / Row 3: 3' split

Pile 244 / Row 4: Offset 3"

Between 244-245: Spalling
Penetrating hole, hole goes up at 45° angle

Pile 245 / Row 1: General note on splitting

Pile 246 / Row 3: Some rip rap
Rows 2 and 3 are close

Pile 248 / Row 3: Offset 2" to left

Pile 249 / Row 2: Offset 5" to right

Pile 249 / Row 4: 1' of exposure, rest is rip rap

Pile 251 / Notes: 20% of load bearing, bearing on pile cap

Pile 251 / Row 3: Offset 2" to right

Pile 252 / Row 1: 2" penetration left side of pile cap

Pile 252 / Row 2: Offset 4" to right

Pile 253 / Row 1: End of pile cap has split, 1" wide, 4" penetration

Pile 255 / Row 3: Large amount of rip rap

Pile 256 / Row 3: Split from top to bottom
10% section loss

Pile 260 / Row 1: Offset 2" to left

Pile 260 / Row 2: Rod going through not pile

Pile 260 / Row 3: Pile offset 3"
Rip rap

Pile 261 / Row 2: Offset 4" to right

Pile 262 / Row 1: 5% section loss

Pile 263 / Row 1: Offset 2" to right
40% section loss

Pile 263 / Row 2: 10% touching

Pile 264 / Row 2: Offset 3" to right

Pile 265 / Row 3: Pile not touching pile cap by 1.5"

241-3

PILE NOTES

PILE NOTES:

Pile 266 / Row 3: Pile split in half, vertically 25% can carry load 75% section loss	Pile 280 / Row 2: 20% section loss	Pile 287 / Row 2: Offset 4" Multiple splits 40% section loss
Pile 267 / Row 1: 50% touching pile cap 1" penetration	Pile 280 / Row 3: Offset 3" Splits	Pile 287 / Row 3: Multiple splits 5% section loss
Pile 267 / Row 2: Offset 3" to left	Pile 281 / Row 1: Splits	Pile 288 / Row 1: 2 piles 15% section loss Multiple splits, 1'-3' 2 nd pile offset 1" to left
Pile 267 / Row 3: General note on splitting 20% touching pile cap	Pile 281 / Row 2: 30% section loss, 6" down to pile	Pile 288 / Row 2: 15% section loss at top of pile cap
Pile 268 / Row 2: 30% section loss from 1"-2" down from pile cap, on pile	Pile 281 / Row 3: Split going forward, 5" down through rip rap (approx. 3.5')	Pile 288 / Row 3: 15-20% section loss at top of pile cap Multiple splits
Pile 268 / Row 3: Not touching cap by 1"	Pile 282 / Row 1: 70% section loss Pile not touching	Pile 289 / Row 1: 25% section loss Multiple splits
Pile 269 / Row 3: Offset 4" to right	Pile 282 / Row 2: 50% section loss	Pile 289 / Row 2: Offset 5" to left 20% section loss
Pile 270 / Row 1: Large split, face of pile cap	Pile 282 / Row 3: 10% section loss Multiple splits	Pile 289 / Row 3: 6-7" missing 3" section loss all around pile cap 30% section loss
Pile 270 / Row 2: Offset 2"	Pile 283 / Row 1: 5"-6" penetration	Pile 290 / Row 2: Split 4' down, 4" wide 15-20% section loss Offset 5" to left 30% deterioration Rip rap about 1'
Pile 270 / Row 3: Offset 3"	Pile 283 / Row 2: Pile goes down instead of up	Pile 291 / Row 1: 20% section loss
Pile 271 / Row 2: 2' behind pile 1 Not touching pile cap	Pile 283 / Row 3: 100% load bearing but multiple splits 20% section loss	Pile 291 / Row 2: Split but okay Offset 3" to left
Pile 272 / Row 2: Offset 3" to right	Pile 284 / Row 1: Beam stops Multiple splits 15% deterioration	Pile 291 / Row 3: Split middle but 100% touching
Pile 272 / Row 3: Not touching by 2" Drift pin holding together Offset 2"	Pile 284 / Row 2: Multiple splits go through pile 20% touching pile cap Offset 5" to left	Pile 292 / Row 1: Split in 4 sections, multiple splits 60% section loss Only 40% touching pile cap
Pile 273 / Row 3: Rip rap	Pile 285 / Row 1: 80% section loss Not touching pile	Pile 292 / Row 2: Split 1' down, 1" wide, 4" penetration
Pile 274 / Row 3: Offset 3" to right	Pile 285 / Row 2: Offset 3" 25% section loss	Pile 292 / Row 3: Split in middle 15% section loss
Pile 275 / Row 2: Offset 5"	Pile 286 / Row 1: 8 x 12 beam going to next level - no load bearing but bolted 100% Split	Pile 293 / Row 1: Split down 2.5', 2" wide, 2" penetration 100% touching
Pile 278 / Row 1: 10% section loss	Pile 286 / Row 2: Offset 5" to left 30% deterioration	Pile 294 / Row 3: 60% section loss
Pile 278 / Row 2: Offset 3"	Pile 286 / Row 3: 25% deterioration, 6" down to top of pile	
Pile 278 / Row 3: 10% section loss General splitting	Pile 287 / Row 1: Split, 1" back, 1.5" wide, 3" penetration	
Pile 279 / Row 1: 40% section loss		
Pile 279 / Row 2: Multiple splits		
Pile 279 / Row 3: Split 3" down, 100% penetration, 2" wide from top to bottom		

PILE NOTES

PILE NOTES:

Pile 294 / Row 1: Split 1' long, 2" penetration	Pile 302 / Row 2: Offset 5" to left
Pile 294 / Row 2: Splits 6' long, 1" wide, ½" penetration	Pile 302 / Row 3: Offset 5" to right of pile cap
Pile 294 / Row 3: Rip rap	Pile 303 / Row 1: Rip rap 0% section loss
Pile 295 / Row 1: Small split, 1' long, 1" wide, 4" penetration	Pile 303 / Row 3: Pile offset 4" to left Rip rap
Pile 296 / Row 1: 15-20% section loss Split 1' long, 4" penetration Pile is split, left side is bearing, goes back to row 2 cap	Pile 304 / Row 1: Offset 4" Pile cap offset to right Pile split 8" long, 2.5" wide, 8"-10" penetration
Pile 296 / Row 3: 80% touching	
Pile 297 / Row 1: Split whole length 80% deterioration End of pile cap split to row 2, 3' long	
Pile 297 / Row 2: Split whole length 80% deterioration	
Pile 297 / Row 3: Offset 4" to left	
Pile 297 / Row 4: Offset 7" to left 2"-3" touching Pile cap has 45% loss	
Pile 298 / Row 1: Splits, 3' down, 1.5" wide, 4" penetration Few splits 50% section loss	
Pile 298 / Row 2: Offset 2" to left No load bearing except 2" x 6" wedge Split both sides of pile	
Pile 298 / Row 3: 5% section loss	
Pile 299 / Row 1: Pile cap end, 20-25% deterioration	
Pile 300 / Row 1: 25% section loss at face on pile cap, end of pile cap	
Pile 300 / Row 2: 2 piles standing next to each other One towards Row 3 is not touching Split 12" down from top of pile	
Pile 301 / Row 2: Face has split 1' long, 1" wide, 4" penetration, goes all way through	
Pile 301 / Row 3: Rip rap	
Pile 302 / Row 1: Pile cap has section loss in center, 12" penetration	

PILE NOTES





PHOTO PLAN



G1 STA 3+50



G2 STA 2+00



G3 STA 0+60 FROM SOUTH WEST



G4 STA 6+70 FROM WEST



G5 STA 6+70 FROM NORTH



G6 TOP OF WALL FROM STA 2+00 TO END



G7 TOP OF WALL FROM EAST AT STA 3+00

Ratings Photograph Section

Photographs specific to inspection ratings.



Photo Number: 1

Description:
AT JOINT STA 0+70-STA 1+10
HEAVY SCALING
APPROXIMATELY 3 FT DOWN
FROM TOP OF WALL

Location:

Rating References:
None



Photo Number: 2

Description:
HEAVY SCALING UP TO JOINT
LOSS OF CONCRETE UP TO 1
FOOT PENE.
2 FT FROM TOP
STA 1+80 - STA 2+00

Location:

Rating References:
None



Photo Number: 3

Description:
HEAVY SCALING FROM TOP TO
WATER LEVEL
MAX PENE. 1'
TYPICAL 6"
STA 5+90 - STA 5+95

Location:

Rating References:
None